

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	e1 1		77 - 1			
Date of Maintenance:	8/25/17 Reason	for Maintenance:	Routine)		,	
Property Address: 15	3833 Ogare 1	and well n	Property Owner's N	ame: Jana 7	teyen)	
Municipality: W	Que 021P:550	82 Property Idea	ntification Number:	:	0	
	0 9 7838 28122	Maintainer Name ar	nd License No. Mev	er Sewer Service Inc	· /I 915	
Maintenance remit iv	01 2 70 30 2070	manitamer rame ar	id Electise No. Mey	CI SCWCI SCIVICC, IIIC	197 197 19	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped			Liquid Level of Tank in			
_ `^ '		Sludge Level in Tank in Scum Level in Tank in				
☐ Sludge and scum measured Do tanks need to be pumped?		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
Li Yes Li No (II I	no provide measurements,	<u> </u>				
1. Access used to ren	nove septage: Maintena	ance Hole 🗌 Other (e	enter authorization c	ode)		
2 Were all covers see	curely replaced? 🗾 Yes	□ No				
			reatment or numn	tank below the one	rating denth or	
evidence of dama	of tank leakage from a se aged, cracked, or structu	rally unsound main	tenance hole cove	ers?	racing depart of	
W.	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes 🗹 No	☐ Yes ☑No		
24	Septic/Holding Tank #2	☐ Yes 🗖 No	□ Yes 🗗 No	☐ Yes 🗹 No	9	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	6	
		t		*		
4. How many gallons	of septage were remove	d?				
Tank #1 <u>/Sひ</u> ひ	_ gal Tank #2 _/ 0 00	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank safe	ety concerns, or oth	er concerns.	
		0.00				
6. Location of septage	e disposal:					
	27 (1200) C (1000) (100)				***	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162