

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a val	id maintenance pe	ermit. This permit m	ust be completed
<u>prior</u> to perfor	ming maintenance activitie	es and remain on	site for the durati	on of the maintenan	ce activity.
Date of Maintenance: 9/6/17 Reason for Maintenance: Routine					
Property Address:	171 73 RD St.	S. P	roperty Owner's Na	ame: Canda ce	Krienke)
Municipality: otta	gove ZIP: 550.	Property Ider	ntification Number:		
Maintenance Permit No	o: <u>e4858w8161</u> M			1	
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)
☑ Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b	pe pumped?	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? X Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes KNo	☐ Yes KNo	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	\square Yes \square No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 $/500$ gal Tank #2		gal Pretreatment	tankga	l Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
	**				
*					
6. Location of septage disposal:					