

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit n	nust be completed	
<u>prior</u> to perfor	ming maintenance activit	ties and remain on	-site for the durat	ion of the maintenan	ce activity.	
	9/7/17 Reason					
Property Address:	9310 9th St.; Elmo zip:550	<u>n. </u>	roperty Owner's N	ame: James	Bjork	
Municipality: Lake	Elmo zip:550	742 Property Ide	ntification Number	:		
Maintenance Permit N	o: <u>m8508j</u> 8/68	Maintainer Name ar	nd License No. <u>//</u>	Joyer / 291:	5	
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks h	NOT pumped)	
X Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
☐ Sludge and scum m	neasured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to I	Sludge + Scum _	Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if i	= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater				
 Were all covers see Is there evidence of 	nove septage: Maintena curely replaced? Yes of tank leakage from a sep aged, cracked, or structur	□ No otic, holding, pretr	eatment or pump	tank below the oper	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes INO	☐ Yes No	☐ Yes No		
	Septic/Holding Tank #2	☐ Yes KNo	□ Yes 🗓No	☐ Yes 🗖 No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	\square Yes \square No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	l?				
Tank #1 / gal Tank #2 / GOO gal Pretreatment tank gal Pump Tank gal						
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.	
10						