

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: $9/9/17$ Reason	for Maintenance:	Routine		
Property Address: 1594 Juya	Eve n.	Property Owner's N	ame: The Gor	us Bigwoo
0	r las	ntification Number		P. J
Maintenance Permit No: 14972 £ 10208 N				 c /I 915
Maintenance Fernit No. 1777 34 703 00 W	iaintainei Naine a	nd License No. Mey	er sewer service, in	C.7 L713
	7			
Maintenance Performed	Tank Mea	surement (must be	completed if tanks	s NOT pumped)
<ul><li>✓ Tank(s) Pumped</li><li>☐ Sludge and scum measured</li></ul>	Liquid Level of Tank in			
	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
Do tanks need to be pumped?				
$\square$ Yes $\square$ No (if no provide measurements)				
1. Access used to remove septage: Amaintenar	nce Hole Other (	enter authorization co	ode)	
			,	
2 Ware all covers securely replaced?   Y   Ves	I NIO			
<ul><li>2. Were all covers securely replaced?  Yes </li><li>3. Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structure</li></ul>		reatment or pump tenance hole cove	tank below the opers?	erating depth or
		reatment or pump itenance hole cove Leaking In	tank below the opers?  Cover Damage	erating depth or
3. Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structura	tic, holding, pret ally unsound mair			erating depth or
3. Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structura	tic, holding, pret ally unsound mair Leaking Out	Leaking In	Cover Damage	erating depth or
3. Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structura  Tank  Septic/Holding Tank #1	tic, holding, pret ally unsound main Leaking Out	Leaking In  Yes 4No	Cover Damage  Yes Yo	erating depth or
3. Is there evidence of tank leakage from a seprevidence of damaged, cracked, or structura  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2	Leaking Out  Yes Mo	Leaking In  Yes INO  Yes INO	Cover Damage  Yes Yoo  Yes Yoo	erating depth or
3. Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structura  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank	Leaking Out  Yes No  Yes No  Yes No	Leaking In  Yes INO Yes NO	Cover Damage  Yes Yoo  Yes Yoo  Yes No	erating depth or
3. Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structura  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?	Leaking Out  Yes No  Yes No  Yes No	Leaking In  Yes INO Yes NO Yes NO Yes NO	Cover Damage  Yes No Yes No Yes No Yes No	
3. Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structura  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?  Tank #1 /500 gal Tank #2 /000	Leaking Out  Yes Mo Yes No Yes Mo Yes Mo	Leaking In  Yes INO Yes NO Yes NO Yes NO	Cover Damage  Yes Yoo Yes No Yes No Yes Yoo	9 <i>00</i> gal
3. Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structura  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?	Leaking Out  Yes Mo Yes No Yes Mo Yes Mo	Leaking In  Yes INO Yes NO Yes NO Yes NO	Cover Damage  Yes Yoo Yes No Yes No Yes Yoo	9 <i>00</i> gal

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162