

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

20 PAST 634 - 1907 NS PAST 80003	o constitute a va	na maintenance pe	ermit. This permit i	must be completed	
<u>prior</u> to performing maintenance activitie	s and remain on	-site for the durati	on of the maintena	nce activity.	
Date of Maintenance: $9/11/17$ Reason for	or Maintenance:	Routine		ARREST CONTRACTOR OF THE STATE	
Property Address: 14460 34th S	T. N.	Property Owner's Na	ame: GREG-CA	ALIGUIRE	
Municipality: <u>BAYTOWN TWSP</u> ZIP: <u>55.08</u>	2 Property Ide	ntification Number:			
Maintenance Permit No: 17099 w 8182 Ma				15	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
☑_Tank(s) Pumped	Liquid Level of Tank in				
☐ Sludge and scum measured	Sludge Level in	Tank in	Scum Level in Tank	in	
Do tanks need to be pumped?	Marin W or M M AND MARINE SALE AND				
☐ Yes ☐ No (if no provide measurements)	if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater				
 2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a septi evidence of damaged, cracked, or structural 	ic, holding, preti			rating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes 风No		
Septic/Holding Tank #2	☐ Yes 🕅 Yo	☐ Yes ☑No	☐ Yes 【XÎNO		
Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☑No	☐ Yes ☑No☐ Yes ☐No		
		,	•		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	gal	
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed?	☐ Yes ☐ No ☐ Yes ☐ No gal Pretreatmen	Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ No ☐ Yes ☐ No ☐ Pump Tank		