Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	y to constitute a va	id maintenance p	ermit. This permit n	nust be completed	
<u>prior</u> to perfor	ming maintenance activi	ties and remain on	site for the durat	ion of the maintenar	nce activity.	
Date of Maintenance:	9/11/17 Reason	n for Maintenance: _	ROUTINE			
Property Address:	1821 OVERLOOP	KLANEN. P	roperty Owner's N	ame: DAWN K	AUL	
	LAKELAND ZIP: 55					
				1		
Maintenance Permit N	o: <i>Z35J2r818</i> 4	Maintainer Name an	d License No//	EYER LYTS		
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of 1	Liquid Level of Tank in			
☐ Sludge and scum m	neasured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100						
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					if 25% or greater	
3. Is there evidence	curely replaced? \(\int\) Yes of tank leakage from a se nged, cracked, or structu	ptic, holding, pretr			ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes □No		
	Septic/Holding Tank #2	☐ Yes ☐No	☐ Yes →No	☐ Yes ☐No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
**	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were remove	d?				
Tank #1 $\int 250$ gal Tank #2 $\int 50$ gal Pretreatment tank gal Pump Tank gal						
5. Other information	: List any troubleshootin	g, minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.	
	ii	. S. C. Walnus constitution in Section (Section 1994)				
6. Location of septage		~ 1				