

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Billor to parite						
	9/12/18 Reason					
Property Address: 7220 LAMAR AVE, S. Property Owner's Name: LORRIE ADAMS						
Municipality: COTTAGE GROVE ZIP:55016 Property Identification Number:						
Maintenance Permit No: 96583v8193 Maintainer Name and License No. Meyer Sewer Service, Inc./L915						
		Tank Meas	urement (must be	completed if tanks	NOT numped)	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
☑ Tank(s) Pumped		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in				
☐ Sludge and scum measured		Sludge + Scum / Liquid Level X 100				
Do tanks need to be pumped?		= % Sludge & Scum Tanks must be pumped if 25% or greater				
$\square$ Yes $\square$ No (if no provide measurements)		in the second se				
1. Access used to remove septage:   Maintenance Hole Other (enter authorization code)						
2. Were all covers securely replaced? Yes No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage	1	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
		1es 110		10 T M T T T T T T T T T T T T T T T T T		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
		15				
4. How many gallons of septage were removed?						
Tank #1 <u>looo</u> gal Tank #2 gal Pretreatment tank gal Pump Tank gal  5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
Cossport	tenk					
6. Location of septage	e disposal:	N-/			-32	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162