

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:		n for Maintenance:				
Property Address:	34 Quehl av	<u>e n. </u>	Property Owner's N	ame: Mark C	pristensen)	
Municipality: Jak	eland ZIP: 55	043 Property Ide	ntification Number:	·		
Maintenance Permit N	o: X1247+8205	Maintainer Name ar	nd License No. Meye	er Sewer Service, Ind	c./L915	
na Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped?		II •	Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater				
						☐ Yes ☐ No (if
1. Access used to ren	nove septage: Mainten	ance Hole 🗌 Other (e	enter authorization co	ode)		
2. Were all covers se	curely replaced?	No				
	of tank leakage from a se aged, cracked, or structu		reatment or pump	tank below the ope	rating depth or	
evidence of dama	iged, cracked, or structu	rany unsound main	tenance note cove	.1.2:		
					_	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Tank Septic/Holding Tank #1	Leaking Out	Leaking In Yes No	Cover Damage Yes No		
•						
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐No		
·	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
A How many gallone	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Yes No Yes No Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	gal	
Tank #1 1200	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Yes No Yes No Yes No Yes No Yes No Res No	☐ Yes ☐ No ☐ tankg	☐ Yes ☐ No al Pump Tank		
Tank #1 <u>1200</u>	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Yes No Yes No Yes No Yes No Yes No Res No	☐ Yes ☐ No ☐ tankg	☐ Yes ☐ No al Pump Tank		
Tank #1 1300	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2 : List any troubleshootin	Yes No Yes No Yes No Yes No Yes No Res No	☐ Yes ☐ No ☐ tankg	☐ Yes ☐ No al Pump Tank		
Tank #1 <u>1200</u>	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2 : List any troubleshootin	Yes No Yes No Yes No Yes No Yes No Res No	☐ Yes ☐ No ☐ tankg	☐ Yes ☐ No al Pump Tank		

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162