

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	and the desired desired		~	on or the mantedia		
Date of Maintenance: _				· · · · · ·		
Property Address:	700 Kurkwood	We. S. P	roperty Owner's Na	me: Jinden 1	Marty	
Municipality: Cattage Shove ZIP: 55016 Property Identification Number:						
Maintenance Permit No: 13138 58754 Maintainer Name and License No. Meyer Sewer Service, Inc./L915						
	<u>'</u>			·	<u></u>	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped  Sludge and scum measured		Liquid Level of Tank in				
		Sludge Level in Tank in   Scum Level in Tank in   Sludge + Scum / Liquid Level X 100				
Do tanks need to b	[5]	11 -	= % Sludge & Scum Tanks must be pumped if 25% or greater			
Yes No (if no provide measurements)						
1. Access used to remove septage: Maintenance Hole 🗆 Other (enter authorization code)						
2. Were all covers securely replaced? Yes No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
evidence of damaged, cracked, or structurally unsound maintenance note covers.						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 【No	☐ Yes No	☐ Yes ☐No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4 Hayr many gallone	of sontage Were removed	17				
4. How many gallons of septage were removed?  Tank #1 1500 gal Tank #2 gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
1.170 - 81 1						
6. Location of septage disposal:						
			-			

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162