

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	<u>9//9//7</u> Reason	for Maintenance: _	(Outine)			
Property Address: 56	11 Julep J.	VacyP	roperty Owner's Na	me: Dree C	Joung	
Municipality: Lake	Elmo ZIP: 550	2 Property Iden	tification Number:		<i>_</i>	
Maintenance Permit No	:W8493n8759	Maintainer Name an	d License No. <u>Meye</u>	r Sewer Service, Inc.,	/L915	
		·	<u> </u>			
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks N	(OT pumped)	
Tank(s) Pumped Sludge and scum measured		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100				
						Do tanks need to be pumped?
☐ Yes ☐ No (if r	o provide measurements)					
1. Access used to rem	ove septage: Maintena	ance Hole 🗌 Other (e	enter authorization co	ode)		
2. Were all covers sec	urely replaced? 👤 Yes	□No				
3. Is there evidence of	f tank leakage from a se ged, cracked, or structu	ptic, holding, pretr	eatment or pump	tank below the opera rs?	ating depth or	
evidence of dama	ged, cracked, or structur	dity disound man				
	Tank	Leaking Out	Leaking In	Cover Damage		
	Tank Septic/Holding Tank #1	Leaking Out Yes	Leaking In	Cover Damage Yes No		
	Septic/Holding Tank #1	☐ Yes No	☐ Yes ☐ Yo	☐ Yes No		
	Septic/Holding Tank #1 Septic/Holding Tank #2	Yes XNo	☐ Yes	☐ Yes XNo		
	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes No ☐ Yes ☐ No		
1	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Tank #1 100	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed 2) gal Tank #2	☐ Yes No	☐ Yes ☐ No	Yes No Yes No Yes No		
Tank #1 100	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	☐ Yes No	☐ Yes ☐ No	Yes No Yes No Yes No		
Tank #1 100	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed 2) gal Tank #2	☐ Yes No	☐ Yes ☐ No	Yes No Yes No Yes No		
Tank #1 100	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes No	☐ Yes ☐ No	Yes No Yes No Yes No		

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162

Maintenance activities must be reported to the Department within 90 days.