

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	9/21/17 Reason	for Maintenance:	Routine								
Property Address:	1730 MC Donald	Dr. Places	roperty Owner's N	ame: Kristino	Tacanstein						
Municipality: Basto	wn These ZIP: 550			7	,						
'//	o: 04852 K8779 N				/1 915						
manifectance retrine iv	0. <u>07000 10777</u>	nameaner name ar	id License 110. meye	or sewer service; me							
EDGE ET BAFFONKELDE AVENDELEN ER EVEN											
Maintenance Performed Tank(s) Pumped Sludge and scum measured		Tank Measurement (must be completed if tanks NOT pumped) Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100									
						Do tanks need to	•	= % Sludge & Scum Tanks must be pumped if 25% or greater			
						☐ Yes ☐ No (II I	no provide measurements)				
1. Access used to ren	n ove septage :	nce Hole 🗌 Other (e	enter authorization co	ode)							
2. Were all covers se	curely replaced? Yes	□No									
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?											
evidence of dame	iged, cracked, or structur	atty unsound main	terrance note cove								
	Tank	Leaking Out	Leaking In	Cover Damage							
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes 🖊 No	☐ Yes 🗖 No	·						
	Septic/Holding Tank #2	☐ Yes ✓ No	☐ Yes Z No	☐ Yes ☐ No							
	Pretreatment Tank	/ □ Yes □ No	∵ Yes □ No	☐ Yes ☐ No	·						
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No							
4 Hayr many gallana	of senters were removed	3									
	of septage were removed gal Tank #2 <u>10-</u> 07		ttank g	al Pump Tank	gal						
•	: List any troubleshooting	-									
		•									
6. Location of septage	disposal:	***************************************									
	_										
		Mayor Coulor Con	vice Inc								

Meyer Sewer Service, Inc.
5325 Manning Ave S
Afton, MN 55001
License# 915 P: 651-459-0162