

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| <u> </u>   | 3                        |  |  |                       | -           |  |
|--|--------------------------|--|--|-----------------------|-------------|--|
| Date of Maintenance: _   | 9/26/17 Reason           | for Maintenance: _                                       | Routine)   |                       | <u>.</u>    |  |
| Property Address: 11400 MANNING AVE.S Property Owner's Name: LINDA MYKLEBUST   |                          |  |  |                       |             |  |
| Municipality: <u>COTTAG</u>  | GE GROVE ZIP: 550        | 23 Property Iden   | tification Number:   |                       | <del></del> |  |
| Maintenance Permit No  | : K672998806 N           | Maintainer Name an                                       | d License No. <u>Meye</u>  | er Sewer Service, Inc | :./L915     |  |
|  | 0                        |  |  |                       | <del></del> |  |
|  | nce Performed            | Tank Measi   | urement (must be   | completed if tanks    | NOT pumped) |  |
| Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped?  |                          | Liquid Level of Tank in                                  |  |                       |             |  |
|  |                          | II   | Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 |                       |             |  |
|  |                          | = % Sludge & Scum Tanks must be pumped if 25% or greater |  |                       |             |  |
| ☐ Yes ☐ No (if r   | no provide measurements) |  |  |                       |             |  |
| 1. Access used to remove septage:   Maintenance Hole Lother (enter authorization code)   |                          |  |  |                       |             |  |
| 2. Were all covers securely replaced? 🗹 Yes 🗆 No   |                          |  |  |                       |             |  |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? |                          |  |  |                       |             |  |
|  | Tạnk                     | Leaking Out  | Leaking In   | Cover Damage          |             |  |
|  | Septic/Holding Tank #1   | ☐ Yes XNo  | ☐ Yes 🎾No  | ☐ Yes XNo             |             |  |
|  | Septic/Holding Tank #2   | ☐ Yes ☐ No   | ☐ Yes ☐ No   | ☐ Yes ☐ No            |             |  |
|  | Pretreatment Tank        | ☐ Yes ☐ No   | ☐ Yes ☐ No   | ☐ Yes ☐ No            |             |  |
|  | Pump Tank                | ☐ Yes ☐ No   | ☐ Yes ☐ No   | ☐ Yes ☐ No            |             |  |
| 4. How many gallons  | of contago wore removed  | d2   |  |                       |             |  |
| 4. How many gallons of septage were removed?  Tank #1 1500 gal Tank #2 gal Pretreatment tank gal Pump Tank gal   |                          |  |  |                       |             |  |
| 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.  |                          |  |  |                       |             |  |
| 6 Standale under deck with landacaping rocks   |                          |  |  |                       |             |  |
| LATO SE DI   |                          |  |  |                       |             |  |
| 6. Location of septage disposal:   |                          |  |  |                       |             |  |

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162