

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	ning maintenance activiti		Site for the durate			
Date of Maintenance: 9/29/17 Reason for Maintenance: Routine						
Property Address: 14571 Ofton Blod. S. Property Owner's Name: Diane Demulling.						
Municipality: Oxtox VzIP:55001 Property Identification Number:						
Maintenance Permit No: y 7026 f 8820 Maintainer Name and License No. Meyer Sewer Service, Inc./L915						
Maintenan	ce Performed	Tank Measu	irement (must be	completed if tanks	NOT (pumped)	
ズ Tank(s) Pumped		Liquid Level of T	Liquid Level of Tank in			
X Tank(s) Pumped Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100						
Do tanks need to be pumped? = % Sludge & Scum Tanks must be pumped if 25% or greater						
☐ Yes ☐ No (if no provide measurements)						
 Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes 🐼No	☐ Yes 🎗 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?						
Tank #1 1260 gal Tank #2 gal Pretreatment tank gal Pump Tank gal Tank #1 gal Tank #2 gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
Customer duy tenk, installed Niser & Manhale Cover						
6. Location of septage disposal:						

Meyer Sewer Service, Inc. 5325 Manning Ave S

Afton, MN 55001

License# 915 P: 651-459-0162