

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	10/3/17 Reason	for Maintenance: _	ROUT	INE	
Property Address: 8280 St. Cronf Jk. S. Property Owner's Name: AL JANKE					
Municipality: DENMARK ZIP: 55082 Property Identification Number:					
Maintenance Permit No: C1476 w8836 Maintainer Name and License No. Meyer Sewer Service, Inc./L915					
Maintenar	ce Performed	Tank Meas	Jrement (must be	completed if tanks	N©T pumped)
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes \(\sqrt{N}\) No (if no provide measurements)		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
		% Staage a scan			
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	,
	Septic/Holding Tank #1	☐ Yes XNo	☐ Yes 🕅 No	☐ Yes A No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed? Tank #1 gal Tank #2 gal Pretreatment tank gal Pump Tank gal 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
6. Location of septage disposal: ST Val					

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162