

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| prior to performing maintenance activities and remain on site for the duration of the maintenance activities   |                        |  |            |                  |  |
|--|------------------------|--|------------|------------------|--|
| Date of Maintenance: 10/16/17 Reason for Maintenance: ROUTINE  |                        |  |            |                  |  |
| Property Address: 11253 ST. CROIX TR.S. Property Owner's Name: JUDY FRE ITAG   |                        |  |            |                  |  |
| Municipality: DENMARK TWSP ZIP: 55033 Property Identification Number:  |                        |  |            |                  |  |
| Maintenance Permit No: 19705 9066 Maintainer Name and License No. Meyer Sewer Service, Inc./L915   |                        |  |            |                  |  |
| Maintenance remit No. 177007 1009 Maintenance Name and Election No. 1889 100 Maintenance No. 188 |                        |  |            |                  |  |
| Maintenance Performed  |                        | Tank Measurement (must be completed if tanks NOT pumped)   |            |                  |  |
| Tank(s) Pumped  Sludge and scum measured Do tanks need to be pumped?  Yes No (if no provide measurements)  |                        | Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater |            |                  |  |
| <ol> <li>Were all covers securely replaced? ✓ Yes □ No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li></ol>  |                        |  |            |                  |  |
|  |                        |  | ☐ Yes XNo  | ☐ Yes ⊠No        |  |
|  | Septic/Holding Tank #1 | ☐ Yes \No  | ☐ Yes ⊅≥No | Man All Marketin |  |
|  | Septic/Holding Tank #2 | ☐ Yes ☐ No   | ☐ Yes ☐ No | ☐ Yes ☐ No       |  |
|  | Pretreatment Tank      | ☐ Yes ☐ No   | ☐ Yes ☐ No | ☐ Yes ☐ No       |  |
|  | Pump Tank              | ☐ Yes ☐ No   | ☐ Yes ☐ No | ☐ Yes ☐ No       |  |
| 4. How many gallons of septage were removed?  Tank #1 1500 gal Tank #2 gal Pretreatment tank gal Pump Tank gal  5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.  |                        |  |            |                  |  |
| 6. Location of septage disposal:   |                        |  |            |                  |  |

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162