

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

prior to performing maintenance activ	ities and remain or	n-site for the durat	ion of the maintena	must be completed nce activity.	
Property Address: 7770 1044 Styre				Copt	
Municipality: Pine Springs ZIP: 65	Property Ide	ntification Number			
Maintenance Permit No: 990269811	Maintainer Name a	nd License No. <u>Pink</u>	y's Environmental Se	wer Service/ L1673	
Maintenance Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements	= % Sludge & Scum Tanks must be pumped if 25% or greater				
 Access used to remove septage: Maintena Were all covers securely replaced? Yes Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure. 	□ No ptic, holding, preti	eatment or pump	tank below the oper	ating depth or	
Tank 	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed Tank #1 /250 gal Tank #2		tank			
5. Other information: List any troubleshooting	, minor repairs cor	nducted, tank safe	ty concerns, or othe	r concerns.	
6. Location of septage disposal:					

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673