

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	0/0-/				ce activity.
<del>-</del>	9/28/17 Reason	for Maintenance: _	(Coutine)		
Property Address: 🚄	149 T Jeal ave	<u> </u>	roperty Owner's N	ame: Lucille	2 Durgo
Municipality:	ton zip: 550	OO/ Property Ide	ntification Number:		_ ' /
Maintenance Permit N	: £864128815	Maintainer Name ar	d License No. Meye	er Sewer Service, Inc.	/L915
	M				
Maintenar  Tank(s) Pumped  Sludge and scum m  Do tanks need to b		Liquid Level of T Sludge Level in Sludge + Scum	¯ank in Гank in / Liquid L	completed if tanks N Scum Level in Tank _ evel X 100 hks must be pumped in	in
☐ Yes ☐ No (if I	no provide measurements)	= % studge & sct	I ai	iks must be pumped in	ZJ% OI BICALCI
d. Access used to see	nove septage: 🗸 Maintena	nee Hele 🗆 Other (s	entor authorization of		
evidence of dama	of tank leakage from a se ged, cracked, or structur Tank	Leaking Out	tenance hole cove	Cover Damage	aoptino.
	Septic/Holding Tank #1	☐ Yes XNo	☐ Yes 🖾No	☐ Yes ☑No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	•
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1500	of septage were removed ≥ gal Tank #2	gal Pretreatmen			

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162