

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

| This section must be completed in its entir   | ety to constitute a va  | lid maintenance p  | ermit. This permit r | nust be completed   |  |
|---|---|--|----------------------|---------------------|--|
| <u>prior</u> to performing maintenance act  | ivities and remain on   | -site for the durat                                      | ion of the maintenar | nce activity.       |  |
| Date of Maintenance: 1/-3-/7 Rea  |   | ^  |                      |                     |  |
|   | Ave N   |  | ame: Rick 1          | LIDII               |  |
| Municipality: LAKE FIMO ZIP: 5  | 9047 Property Ide   | ntification Number:                                      |                      |                     |  |
| Maintenance Permit No: Y6289m96   |   |  |                      | war Candaa / 1 1673 |  |
|   | 2 maintainer Haine ar   | id Electise No. Tillk                                    | y 3 Environmentat se | wer service/ L16/3  |  |
| Maintenance Performed   | Tank Meas   | Tank Measurement (must be completed if tanks NOT pumped) |                      |                     |  |
| Tank(s) Pumped  | Liquid Level of   | Liquid Level of Tank — in                                |                      |                     |  |
| ☐ Sludge and scum measured  | Sludge Level in   | Sludge Level in Tank in Scum Level in Tank in            |                      |                     |  |
| Do tanks need to be pumped?   | pumped?   Sludge + Scum   |  |                      |                     |  |
| $\square$ Yes $\square$ No (if no provide measurement   | no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater |  |                      |                     |  |
| 1. Access used to remove septage:   Maint   | enance Hole Other (e  | enter authorization co                                   | ode)                 |                     |  |
| 2. Were all covers securely replaced?  Y  |   |  |                      |                     |  |
| <ol><li>Is there evidence of tank leakage from a<br/>evidence of damaged, cracked, or struc</li></ol> |   |  |                      | ating depth or      |  |
| Tank  | Leaking Out   | Leaking In   | Cover Damage         |                     |  |
| Septic/Holding Tank #1  | ☐ Yes ☐ No  | ☐ Yes ☐ No   | ☐ Yes ☐ No           |                     |  |
| Septic/Holding Tank #2  | ☐ Yes ☐ No  | ☐ Yes ☐ No   | ☐ Yes ☐ No           |                     |  |
| Pretreatment Tank   | ☐ Yes ☐ No  | ☐ Yes ☐ No   | ☐ Yes ☐ No           |                     |  |
| Pump Tank   | ☐ Yes ☐ No  | ☐ Yes ☐ No   | ☐ Yes ☐ No           |                     |  |
| 4. How many gallons of septage were remov   | ved?  |  |                      |                     |  |
| Tank #1 <u>/500</u> gal Tank #2   | gal Pretreatment  | tankga   | al Pump Tank         | gal                 |  |
| 5. Other information: List any troubleshoot   | ing, minor repairs cor  | nducted, tank safe                                       | ty concerns, or othe | er concerns.        |  |
| Too old for manhale per b   |   |  |                      |                     |  |
|   |   |  |                      |                     |  |
| 6. Location of septage disposal:  |   |  |                      |                     |  |

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673