

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

<u>prior</u> to performing maintenance activi	to constitute a va	lid maintenance pe	rmit. This permit m	nust be completed	
Date of Maintenance: 12-20-17 Reason			on or the maintenan	ce activity.	
		A CONTRACTOR OF THE PARTY OF TH	ne		
Property Address: 185 Benns Lane	,	Property Owner's Na	me: Kennety	Kaufhole	
Municipality: Mantoncedi zip: 551	Property Ide	ntification Number:			
Maintenance Permit No: 68831610362	Maintainer Name ar	nd License No. Pinky	's Environmental Sev	ver Service/ L1673	
Maintenance Performed	Tank Meas	surement (must be	completed if tanks N	NOT pumped)	
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank — in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements)	= % Sludge & Sci	um Tan	ks must be pumped i	f 25% or greater	
1. Access used to remove septage: Maintena	ance Hole Other (e	enter authorization cod	de) 75016		
2. Were all covers securely replaced? Yes					
Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure				ating depth or	
			3 1c3 _ 110		
Tank	Leaking Out	Leaking In	Cover Damage		
Tank	Leaking Out	Leaking In	Cover Damage		
Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No tank ga	Cover Damage Yes No Yes No Yes No Yes No Yes No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed Tank #1 1 2 5 gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No tank ga	Cover Damage Yes No Yes No Yes No Yes No Yes No		

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673