## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be com	pleted in its entirety	to constitute a v	alid maintenance p	ermit. This permit	must be complete	
<u>prior</u> to performing	g maintenance activit	ies and remain o	n-site for the durat	ion of the mainten	ance activity.	
Date of Maintenance: 12	//// Reason	for Maintenance:	putin	2	,	
Property Address: 1990	Roscia				+ Shearer	
Municipality: <u>La dela</u>	nel ZIP: <u>\$50</u>	Y3 Property Ide	entification Number:			
Maintenance Permit No: χ						
			THE LICENSE NO. 1 HIK	3 Environmental 3	ewer service/ L16/.	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank — in				
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove	septage: Maintenan	ce Hole Other				
2. Were all covers securely			chief ddillonzation co	de) 10 010		
<ol><li>Is there evidence of tan evidence of damaged.</li></ol>	cracked, or structura	illy unsound main	reatment or pump t	ank below the ope	rating depth or	
	ged, cracked, or structurally unsound maintenance hole covers?   Yes No					
Management	Tank	Leaking Out	Leaking In	Cover Damage		
Septi	c/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septi	c/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretr	eatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump	o Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of sep	tage were removed?				e e	
Tank #1 /2.52 gal	Tank #2	gal Pretreatmen	t tankga	Pump Tank	gal	
5. Other information: List	any troubleshooting,	minor repairs co	nducted, tank safet	v concerns or othe	er concerns	
		Legillik neette pre 111		, concerns, or our	concerns.	
6. Location of septage dispo	sal:					

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673