

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entir <u>prior</u> to performing maintenance act				
			on or the maintenar	ice activity.
Date of Maintenance: 12-6-19 Rea	son for Maintenance: _	Kouthe		
Property Address: 998) Anolo	act No. P	roperty Owner's Na	ame: Jerone +	mary mcka
Municipality: Stellwater ZIP:5	Seg Property Ider	ntification Number:		8
16				
Maintenance Permit No: £ 8230 v 6173	Maintainer Name an	d License No. Pinky	y's Environmental Se	wer Service/ L1673
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped	umped Liquid Level of Tank ——— in			
	Sludge and scum measured Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measureme	e measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Main	tenance Hole 40ther (e	nter authorization co	ode)	
2. Were all covers securely replaced?				
 We're all covers securely replaced:		eatment or numn	tank below the one	ating denth or
evidence of damaged, cracked, or struc				denig depair of
	1 -11 - 0 -	1 - 11 1		
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were remo	ved?			
Tank #1 / 500 gal Tank #2	gal Pretreatment	tankg	al Pump Tank	gal
5. Other information: List any troubleshoo	ting, minor repairs co	nducted, tank safe	ty concerns, or other	er concerns.
Munhole 4-5 Feet deep				
6. Location of septage disposal:				

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673