

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

| prior to perfo | completed in its entirety | to constitute a va | llid maintenance p | ermit. This permit | must be completed | |
|-------------------------------------|--|------------------------------------|--|-----------------------|--------------------|--|
| prior to perio | rming maintenance activi | ties and remain or | -site for the durat | ion of the maintena | nce activity. | |
| Date of Maintenance: | 1-8-18 Reason | for Maintenance: | Routin | _ | | |
| Property Address: 1 | 163 Quant A | re. Mc | Property Owner's N | ame: Ron | talverson | |
| Municipality: <u>SM</u> | WUTU ZIP: SS | 87 Property Ide | ntification Number | | 0 | |
| | 10:066251 10398 | | | | | |
| | The same of the second section of the section of the second section of the sectio | The state of | id Electise No. rilk | y s chvironinentat se | wer service/ L16/3 | |
| Maintenance Performed | | Tank Meas | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | Liquid Level of Tank — in | | | | |
| Sludge and scum measured | | Sludge Level in | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | | |
| Yes No (if no provide measurements) | | = % Sludge & Scr | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to ren | nove septage: Maintena | nce Hole Cother (e | | | | |
| | curely replaced? Yes | | | , | | |
| 3. Is there evidence | of tank leakage from a sep aged, cracked, or structur | otic, holding, pretr | eatment or pump tenance hole cove | tank below the oper | ating depth or | |
| | Tank | Leaking Out | Leaking In | Cover Damage | | |
| | Septic/Holding Tank #1 | ☐ Yes ☐No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | of septage were removed | | | | | |
| Tank #1 750 | gal Tank #2 750 | _gal Pretreatment | tankga | l Pump Tank | gal | |
| 5. Other information: | List any troubleshooting, oo old for mark | , minor repairs cor | ducted, tank safet | ty concerns, or othe | r concerns. | |
| 5. Location of septage | disposal: | | | | | |

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673