Bennit # 25210n 1061

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 4/15/16 Reason for Maintenance: PM			
Property Address: 1837 Racine Ave 5 Property Owner's Name: Paul Rutz			
Municipality: Washington County State MN Zip Code 55043 GEO Code/Property I.D. #:			
What was done to the system?	Tank Me	easurements (must be co	ompleted if tanks NOT pumped)
▼ Tank(s) Pumped			
Sludge and scum measured.	Liquid Level of Ta	ank in. Sludge	Level in. Scum Level in.
Do tanks need to be pumped?	T-1-1/51 1 6		*
Yes No (If no provide measurements)	Total (Sludge + S	cum) / Liquid Le	evel = % Sludge & Scum
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below) * Tank must be pumped if this value is greater than 25%.			
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain			
Explanation:			
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement: Tank top - no cover found: (owner's name), refuse to allow the removal of solids and liquids through the maintenance			
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.			
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit			
Tank#1 Tyes Tho Verificatio Method Used: Unknown; no access other than 6"			
Tank#2 Yes No Verificatio Method Us		,	pipe.
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?			
Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	Yes No	☐ Yes ◯ No	☐ Yes 📉 No
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No
Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No
Pump Tank	Yes No	☐ Yes ☐ No	
6. How many gallons of septage were removed?		1 163 1 140	Yes No
Tank #1 \AGO Tank #2			
10-	_		ump Tank
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.			
Continued PVC pipe at dist box, line clear tank to dist			
3. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.			
Maintainer's Name: Olson's Sewer Service Maintainer's Address: 17638 Lyons Street NW Forest Lake MN 55025			
Maintainer's License #: 216 Maintainer's Phone #: 651-464-2802			
Maintainer's Signature		Date:	