Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	ampleted in its entirety			This normit mus	t he completed	
prior to perform	This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complete prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
prior to perior	ning maintenance activiti	ies and remain on-s	ite for the duration	on of the maritenance	detivity.	
Date of Maintenance:	7-6-18 Reason	for Maintenance:	Beg M	a 2 1 7		
Property Address:	15/ Lerry		operty Owner's Na	me: Boad Bo	gacher	
//) ZIP: 550	20	tification Number:		7 -	
Municipality: Hug					-	
Maintenance Permit No	0: V179/3/1506 M	Maintainer Name and	d License No. Smili	e's Sewer Service/L242	.8	
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks NO	T pumped)	
		Liquid Level of T	Liquid Level of Tank in			
. ☑ Tank(s) Pumped		Sludge Level in 7	Sludge Level in Tank in Scum Level in Tank in			
☐ Sludge and scum measured		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Sludge & Scu	ım Tar	nks must be pumped if	25% or greater	
\square Yes \square No (if no provide measurements)						
	nove septage: Maintena		nter authorization co	ode) Pre 19	80	
2. Were all covers see	curely replaced? \square Yes	□ No				
3. Is there evidence of	of tank leakage from a se aged, cracked, or structu	ptic, holding, pretr	eatment or pump tenance hole cove	tank below the operators? \square Yes $\c \Box$ Yo	ting depth or	
		1 11 - 0 1	Laskingto	Cover Damage		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes INO	Cover Damage Yes No		
		1/	. /			
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☐No	☐ Yes ☐ No		
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 750	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No ☐ d? ☐ gal Pretreatment	☐ Yes ☐ No ☐ tank — g	☐ Yes ☐ No		
Tank #1 750	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ d? ☐ gal Pretreatment	☐ Yes ☐ No ☐ tank — g	☐ Yes ☐ No		
Tank #1 750	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No ☐ d? ☐ gal Pretreatment	☐ Yes ☐ No ☐ tank — g	☐ Yes ☐ No		
Tank #1 750 5. Other information	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2 : List any troubleshooting	☐ Yes ☐ No ☐ d? ☐ gal Pretreatment	☐ Yes ☐ No ☐ tank — g	☐ Yes ☐ No		
Tank #1 750	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2 : List any troubleshooting	☐ Yes ☐ No ☐ d? ☐ gal Pretreatment	☐ Yes ☐ No ☐ tank — g	☐ Yes ☐ No		
Tank #1 750 5. Other information	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2 : List any troubleshooting	☐ Yes ☐ No ☐ d? ☐ gal Pretreatment	Yes No Yes No Yes No Yes No tankg nducted, tank safe	☐ Yes ☐ No		

23893 Pomroy Ave N Scandia MN 55073 651-433-3934