

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	7-11-18 Reason 1	for Maintenance:	Regula		
Property Address: 7652 Killiam Ave N. Property Owner's Name: Linda le sh					
Municipality: Scar	70/2 ZIP: 550-	7 ≥ Property Ide	entification Number	r•	7/
Maintenance Permit N	10: <u>r28/1 e/1439</u> M	aintainer Name	and License No. Ole	onla Couran Couries (I	244
		antaner Hame e	and License No. Ots	oli s sewer service/L	<u> </u>
Principle of Shirts			4-2-0-1		
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?.		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measurements)		ranks must be pumped if 25% or greater			
1. Access used to rer	nove septage: 🏻 Maintenand	e Hole Other	enter authorization c	oda)	
<ul> <li>2. Were all covers securely replaced?  Yes No</li> <li>3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?  Yes No</li> </ul>					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes X No	☐ Yes No	☐ Yes ☒\No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	□, Yes □ No	☐ Yes ☐ No	
Tank #1_1150	of septage were removed?  gal Tank #2 ; List any troubleshooting, r	gal Pretreatmen ninor repairs co	t tank ganducted, tank safe	al Pump Tank ty concerns, or othe	gal er concerns.
6. Location of septage	disposal: Mutro				

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082

Maintenance activities must be reported to the Department within 90 days.