

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entiret	y to constitute a	alid maintenance p	ermit. This permit i	must be complete	
<u>prior</u> to perf	orming maintenance activi	ities and remain o	n-site for the durat	ion of the maintena	nce activity.	
Date of Maintenance	: 4-20-16 Reason	n for Maintenance				
Property Address:	10563 230th	STN	Property Owner's N	ame: Michael	Mac Anda	
Municipality:	ZIP:	Property Id	entification Number:	:		
Maintenance Permit	No: <u>69388 w 1062</u>	Maintainer Name	and License No. OS	SI - 7216		
Mainten	ance Performed	Tank Mea	asurement (must be	completed if tanks I	NOT pumped)	
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		TI	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)	11	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	ecurely replaced? —Yes of tank leakage from a sep aged, cracked, or structur	otic, holding, pret	reatment or pump t	ank below the operars?	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🖾 No	☐ Yes ØNo	☐ YeS No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed?	?				
Tank #1 1250 gal Tank #2 g		gal Pretreatmen	t tank gal	Pump Tank	gal	
	: List any troubleshooting,				concerns.	
5. Location of septage	disposal:					
	and					