



Client/ Address:		14364 15th street north			Legal Description/ GPS:						
Soil parent material(s): (Check all that apply) <input type="checkbox"/> Outwash <input type="checkbox"/> Lacustrine <input checked="" type="checkbox"/> Loess <input type="checkbox"/> Till <input type="checkbox"/> Alluvium <input checked="" type="checkbox"/> Bedrock <input type="checkbox"/> Organic Matter											
Landscape Position: (check one) <input type="checkbox"/> Summit <input type="checkbox"/> Shoulder <input checked="" type="checkbox"/> Back/Side Slope <input type="checkbox"/> Foot Slope <input type="checkbox"/> Toe Slope Slope shape							LL				
Vegetation		grass, lawn		Soil survey map units		Slope%		4.0		Elevation:	
Weather Conditions/Time of Day:			cloudy, 2:00 PM				Date		05/12/16		
Observation #/Location:		B1				Observation Type:		Auger			
Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	I----- Structure-----I				
							Shape	Grade	Consistence		
0-11	Silt Loam		10YR 3/3	-			Blocky	moderate	friable		
11-37	Silt Loam		10YR 4/4				Blocky	Moderate	Friable		
37-52	Bedrock		5Y 8/4				Massive	Structureless	Rigid		
Comments	bedrock at 37 inches										
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.											
Alex Pepin						C9844			5/12/2016		
(Designer/Inspector)			(Signature)			(License #)			(Date)		