



## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Data of Haint	5/10/2010		T			
Date of Maintenanc	7	n for Maintenance	Soutens			
Property Address:	1331-19940 St	No-	Property Owner's	Name: T. Eolu	nan	
Municipality: <u>S</u> c	andia ZIP:	Property Ide	entification Numbe	r:		
Maintenance Permi	No. of the second			on's Sewer Service/L	216	
	3		, t			
Mainte	nance Performed	Tank Mea	Surement (must be	a completed if tanks	NOT summed	
and the remorned			Tank Measurement (must be completed if tanks NOT pumped)			
<ul> <li>▼ Tank(s) Pumped</li> <li>☐ Sludge and scum measured</li> <li>Do tanks need to be pumped?</li> <li>☐ Yes ☐ No (if no provide measurements)</li> </ul>		11	Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
		Studge Level in				
		- % Studge & Sc				
		)   - % Studge a sc				
1. Access used to r	emove sentage: M Maintan	anan Hala VII Oshan (				
	emove septage: Majngen	Jack Suit	incomplete authorization of	ode)		
2. Were all covers	securely replaced? 🗀 Yes	□ No				
3. Is there evidence	e of tank leakage from a se	ptic, holding, pret	reatment or pump	tank below the ope	erating depth or	
evidence of dar	maged, cracked, or structu	rally unsound mair	ntenance hole cove	ers? 🗌 Yes 🗌 No		
	Tank	Leaking Out	Leaking In	Cover Damage	ľ	
	Septic/Holding Tank #1	☐ Yes 🕅 No	☐ Yes 🗓 No	☐ Yes 🏻 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank					
	Freueatment rank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallon	s of septage were removed	1?				
Tank #1/000	gal Tank #2 250	_ gal Pretreatment	t tank a	al Pump Tank	anl	
. Other informatio	n: List any troubleshooting	minor repairs co	nducted tank safe	at rump rank	gal	
	a.e. a.i.y a oabtestiootilig	, milor repairs cor	raucteu, tailk safe	ty concerns, or other	er concerns.	
		1				
. Location of septag	ge disposal: Stan	mition				
1						

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025

License# 216 P: 651-464-2082