

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	13 sept 18 Reason	for Maintenance:	Rea Maint	- Ion of the maintene	ince activity.	
	190 Kelvin Ave					
Municipality: (aka	£1110 ZIP: 550	AUZ Property Ide	entification Number	allie. 10th Roger	\$	
Maintenance Permit	No: 43082 j 12995	Maintain an Name a	addiagae Na Cai			
Maintenance i Cimie i	10.113002 112 113	maintainer name a	nd License No. Smil	.ie's Sewer Service/L	_2428	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped			Liquid Level of Tank in			
☐ Sludge and scum i			Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to	•	= % Sludge & Sc		nks must be pumped		
☐ Yes ☐ No (If	no provide measurements)				3	
1. Access used to re	move septage: 🗆 Maintena	ance Hole 🔀 Other (enter authorization c	ode)		
2. Were all covers se	ecurely replaced? 🛭 Yes	□No				
3. Is there evidence	of tank leakage from a se	ptic, holding, pret	reatment or pump	tank below the ope	rating depth or	
evidence of dam	aged, cracked, or structu	rally unsound main	itenance hole cove	rs? 🗌 Yes 🖾 No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ☑No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1,/000	gal Tank #2	_ gal Pretreatmen	t tank——— g	al Pump Tank	gal	
5. Other information	: List any troubleshooting	,, minor repairs co	nducted, tank safe	ty concerns, or oth	er concerns.	
6. Location of septag	e disposal: Land A	Male)				
	2420 /1	1-6				

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073

License# 2428 P: 651-433-3934