

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	7/21/18 Reason f		Mainleman	00 .	
0 111					
Municipality: Forest Lake ZIP:55025 Property Identification Number:					
Maintenance Permit No: 185696/3096 Maintainer Name and License No. Olson's Sewer Service/L216					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Taulifa Barra d		Liquid Level of Tank in			
☐ Tank(s) Pumped		Sludge Level in Tank in Scum Level in Tank in			
Sludge and scum me		Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
L Tes L NO (II II	to provide measurements)				
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes					
				Cover Damage	ĺ
	Tank	Leaking Out	Leaking In		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons Tank #1_1300	Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ No ?	☐ Yes ☐ No	☐ Yes ☐ No	gal
Tank #1 1300	Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ No ? gal Pretreatmen	☐ Yes ☐ No ☐ Yes ☐ No t tank——— g	☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☐ No☐ al Pump Tank	gal
Tank #1 1300	Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ No ? gal Pretreatmen	☐ Yes ☐ No ☐ Yes ☐ No t tank——— g	☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☐ No☐ al Pump Tank	gal ner concerns.
Tank #1 1300	Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No gal Pretreatmen minor repairs co	☐ Yes ☐ No ☐ Yes ☐ No t tank——— g	☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☐ No☐ al Pump Tank	gal ner concerns.

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025

License# 216 P: 651-464-2082