

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit i	must be completed
<u>prior</u> to perfor	ming maintenance activit	ies and remain on	-site for the durat	ion of the maintena	nce activity.
Date of Maintenance:	A	for Maintenance:	Routin	ie Maint	ienance
Property Address: <u></u>	oHLOS 2nd	STN	Property Owner's N	lame: Jim M	Icatee
Municipality: LOK	eland zip.550	<u>H</u> 3 Property Ide	ntification Number	:	a .
Maintenance Permit N	0:1 <u>49233f0195</u> A	Maintainer Name a	nd License No. 🔼	ade Madsen	#83692
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers see Is there evidence of 	nove septage: A Maintena curely replaced? Yes of tank leakage from a sep aged, cracked, or structure	□ No otic, holding, pret	reatment or pump	tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ∰No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 <u>1500</u> gal Tank #2		gal Pretreatment tankg		gal Pump Tank	gal
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or oth	er concerns.