

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety t				
	ning maintenance activiti			/	
Date of Maintenance:	4-14-16 Reason	for Maintenance: _	schedy led	Mainte.	nance
Property Address: 10124 6776 Ln W Property Owner's Name: Christa Shores					
Municipality: 54/16	juster IIP: 550	82 Property Ider	tification Number:		
Maintenance Permit No	: 1976350689N	— Naintainer Name an	d License No. 2/a	de Madson a	83692
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if n	o provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence o	rurely replaced? 💢 Yes If tank leakage from a sep ged, cracked, or structure	tic, holding, pretr	eatment or pump tenance hole cover	tank below the oper rs?	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	□ Yes ♣No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 <u>1500</u> gal Tank #2		_gal Pretreatmen	t tankga	al Pump Tank	gal
5. Other information:	List any troubleshooting	, minor repairs co	nducted, tank safe	ty concerns, or othe	er concerns.