

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance po	ermit. This permit r	nust be completed	
<u>prior</u> to perfor	ming maintenance activi	ies and remain on	-site for the durati	ion of the maintena	nce activity.	
Date of Maintenance:	4-13-16 Reason	for Maintenance:	schedale	of prairie	mance	
Property Address:	1993 Boutwe	1 Rd	Property Owner's N	ame: Matt 5	erberich	
Municipality: 54/1	Inster ZIP:550	?2 Property Ide	ntification Number:	i		
Maintenance Permit N	0: <u>+9805K0U</u> 88	Maintainer Name ar	nd License No. <u>Ao</u>	ns sealers	Gerut & 2554	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
3. Is there evidence	curely replaced? Yes of tank leakage from a se aged, cracked, or structur	ptic, holding, preto ally unsound main	tenance hole cove	ers?	rating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes No	☐ Yes 4 No	☐ Yes (TNo		
	Septic/Holding Tank #2	☐ Yes TNo	☐ Yes PNo	☐ Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 1000	gal Tank #2 1000	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting	s, minor repairs co	nducted, tank safe	ety concerns, or other	er concerns.	