

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

Danis

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance;	0-19-18 Reason f	or Maintenance: _	Reg Ma	in I	- 4
Property Address: 42	545 170m ST	P	roperty Owner's N	ame: Dave No	rdhayson
Municipality: Hive	ZIP: 5503	2	ntification Number:		,
Maintenance Permit No: 44126/13653 Maintainer Name and License No. Boss Pumping/L2428					
	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		.a _1.co.iso 1101 <u>_2.cs</u>	. amping/ 22 120	
		Tank Hoas	uramant (must be	completed if table	NOT numbed)
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Sludge & Scum Tanks must be pumped if 25% or greater			
$\square$ Yes $\square$ No (if no provide measurements)					
1. Access used to remove septage:   Maintenance Hole Dother (enter authorization code)					
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers?   Yes Lino					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ♠No	☐ Yes ☐ No	☐ Yes ☐No	
		□ Yes ☑NO	☐ Yes ☐No	□ Yes ♣No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1_600_ gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
6. Location of septage	disposal: 1/all		1 0000	1 Lapla	
o. Location of septage	disposat.		CVIVE	THE Y	
				, /	

**Boss Pumping PO BOX 534** 

Forest Lake, MN 55025

License# 2428 P: 651-466-0800