

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: Doct B Reason for	or Maintenance:	Kea Main		
Property Address: Ma 6817 170th 51.	N	Property Owner's N	ame: <u>Celeste</u>	Porter
Municipality: Hugo ZIP: 550		ntification Number:		
Maintenance Permit No:	aintainer Name a	nd License No. Smil	ie's Sewer Service/L	2428
K 4873 13399				
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Tank in		
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
\square Yes \square No (if no provide measurements)				
1. Access used to remove septage: Maintenance	ce Hole Other (enter authorization co	ode)	ar.
2. Were all covers securely replaced? 💢 Yes 🗆			,	
3. Is there evidence of tank leakage from a sept		eatment or pump	tank below the ope	rating depth or
evidence of damaged, cracked, or structural				
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes 🄀 No	☐ Yes 🗹 No	☐ Yes 🛮 No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	\square Yes \square No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
-				
4. How many gallons of septage were removed?				
	gal Protroatmon	t tank g	al Pump Tank	gal
Tank #1 gal Tank #2	gat Fretteatmen	t tarik——— g	at Fullip Falls	gai
Tank #1 gal Tank #2 5. Other information: List any troubleshooting,				

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073

License# 2428 P: 651-433-3934