

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT



GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## **Subsurface Sewage Treatment System Maintenance Permit**

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	10.1111.10		7						
Date of Maintenance: _		for Maintenance:		,					
Property Address: 22	1389 KIRL COUR	F N F	roperty Owner's N	ame: Traci Hon	ffe				
Municipality: <u>Scano</u>	lia zip: 550	23 Property Idea	ntification Number:						
Maintenance Permit No	:d4624e13117	Naintainer Name ar	nd License No. Olso	n's Sewer Service/Li	216				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)							
☐ Sludge and scum measured		Liquid Level of Tank in Scum Level in Tank in in							
						Do tanks need to b			Sludge + Scum / Liquid Level X 100   = % Sludge & Scum Tanks must be pumped if 25% or greater
☐ Yes ☐ No (if no provide measurements)		= % studge & sci	= % Studge & Scum Tanks must be pumped if 25% of greater						
1. Access used to remove septage: Maintenance Hole  Other (enter authorization code)									
2. Were all covers see	curely replaced? A Yes	□No							
			eatment or pump	<ol> <li>Were all covers securely replaced? ✓ Yes ☐ No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or</li> </ol>					
evidence of damaged, cracked, or structurally unsound maintenance hole covers?   Yes  No									
					•				
	ged, cracked, or structur	ally unsound main	tenance hole cove	ers?    Yes    No					
	ged, cracked, or structur	ally unsound main	Leaking In	Cover Damage					
	ged, cracked, or structur  Tank  Septic/Holding Tank #1	Leaking Out	Leaking In  Yes Aro	Cover Damage  Yes No					
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out  Yes No	Leaking In  ☐ Yes ☐ No	Cover Damage  Yes No  Yes No  Yes No					
4. How many gallons Tank #1   000	Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed  gal Tank #2  List any troubleshooting	Leaking Out  Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Yes No Yes No	gal				

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025

License# 216 P: 651-464-2082