

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Pd

**Subsurface Sewage Treatment System Maintenance Permit** 

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	7-31-/8 Reason	n for Maintenance:	Royalar			
	850 Grwell Are			Name: Lounge	Holmgon	
Municipality: Yame ZIP:55047 Property Identification Number:						
Maintenance Permit No: 15560 No. 1841 Maintainer Name and License No. Olson's Sewer Service/L216						
				SIL S SCHOL SCHICE!	210	
Matuenna	nce Performed	Tank Hox	#1.14 mm a u.S. fem. 1/4 3.			
	псе Репогтед	THE RESERVE AND ADDRESS OF THE PARTY OF THE	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		III .	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in			
Sludge and scum measured Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
	be pumpea? no provide measurements)	- % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenance Hole  Other (enter authorization code)						
<ol> <li>Were all covers securely replaced?  Yes  No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or</li> </ol>						
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No						
	Tank	Leaking Out			1	
			Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🎾 No	☐ Yes XNo	☐ Yes ⊠No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes 🛱 No	☐ Yes ☑ No	☐ Yes ☑ No		
					"	
4. How many gallons of septage were removed?						
Tank #1 1750 gal Tank #2 gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
6. Location of septage	disposal: Weto	St. Paul	1			

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082