

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

<u>prior</u> to performing maintenance activit			of the mantena	iou diouvily:	
Date of Maintenance: 10-26-18 Reason	for Maintenance: _	131-19	P. 11		
Property Address: 14/20 Square Lake TR Property Owner's Name: Bill Mann					
Municipality: ZIP:5508 Property Identification Number:					
Maintenance Permit No: 5068/7/3695 Maintainer Name and License No. Olson's Sewer Service/L216					
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
√ Tank(s) Pumped	Liquid Level of T	ank in		i n	
Sludge and scum measured	Studge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Studge - Stuff				
☐ Yes ☐ No (if no provide measurements)	II = % Studge & Scuit Tailes must be painted it zero				
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
 2. Were all covers securely replaced?					
3 is there evidence of tank leakage from a se	DCC, NOIGHE, DECL	Cornicis of house	CONTINUE IN COLUMN 1.		
Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure	ptic, notding, pred rally unsound main	tenance hole cove	rs? 🗌 Yes 🔊 No		
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure. Tank	rally unsound main Leaking Out	tenance hole cove	rs? Yes No Cover Damage		
evidence of damaged, cracked, or structur	rally unsound main	Leaking In	Cover Damage		
evidence of damaged, cracked, or structure	rally unsound main Leaking Out	Leaking In Yes No	Cover Damage Yes No		
evidence of damaged, cracked, or structure Tank Septic/Holding Tank #1	Leaking Out Yes \(\bigcirc \text{No} \)	Leaking In Yes No	Cover Damage Yes No		
evidence of damaged, cracked, or structure Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes Aho Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were remove Tank #1 Tank Pump Tank Tank #1 Tank #1 Tank #1 Tank #2 Tank #2	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were remove Tank #1 Tank Pump Tank Tank #1 Tank #1 Tank #1 Tank #2 Tank #2	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were remove Tank #1 Tank Pump Tank Tank #1 Tank #1 Tank #1 Tank #2 Tank #2	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal	

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082