

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entired prior to performing maintenance active Date of Maintenance: $5 - 8 - 18$ Reason	rities and remain on on for Maintenance:	site for the durati	ion of the maintena	nce activity.
Property Address: 2769 Legion F Municipality: Lake Elmo zIP: 559 Maintenance Permit No: <u>C 2997 i 10709</u>	Property Ider	ntification Number:	-	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
<ul> <li>✓ Tank(s) Pumped</li> <li>☐ Sludge and scum measured</li> <li>Do tanks need to be pumped?</li> <li>☐ Yes ☐ No (if no provide measurement</li> <li>1. Access used to remove septage: ☐ Mainter</li> </ul>	Sludge Level in Sludge + Scum = % Sludge & Scu	/ Liquid L um Ta	Scum Level in Tank evel X 100 nks must be pumped	if 25% or greater
2. Were all covers securely replaced?   3. Is there evidence of tank leakage from a securely replaced?   4. Yes all covers securely replaced?   5. Yes all covers securely replaced?   6. Yes all covers securely replaced?   7. Yes all covers securely replaced?   8. Yes all covers securely replaced?   8. Yes all covers securely replaced?   9. Yes all covers securely re	eptic, holding, pretr			rating depth or
Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes Mo	☐ Yes ☐ No	
Septic/Holding Tank #2  Pretreatment Tank	☐ Yes ☐ No☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No	
4. How many gallons of septage were remove		Yes No	Yes No	
Tank #1 1500 gal Tank #2  5. Other information: List any troubleshootin  6. Location of septage disposal:	ng, minor repairs cor	nducted, tank safe		er concerns.
Pink	xy's Environmental Se	wer Service Inc.		

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.