

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	ty to constitute a va	alid maintenance n	ermit. This permit r	nust be completed	
prior to performing maintenance activ	vities and remain or	-site for the durat	ion of the maintenar	nust be completed	
P 1 14	on for Maintenance:		tine	ice delivity.	
Property Address: 16436 7th St	110	Property Owner's N	ame: Anthon	Jamlon	
Municipality: Lafeland ZIP550	Property Ide	ntification Number	0	10000	
Maintenance Permit No: 12959210105				wer Consiso / L1473	
			y 3 Elivirolimentat Sev	wei service/ L16/3	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank — in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements	s) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Mainter	ance Hole Other (
2. Were all covers securely replaced? Yes		addionization et	ac Dup & n	and De l'all	
 Is there evidence of tank leakage from a see evidence of damaged, cracked, or structu 	spric, notaing, pretr	tenance below	tank below the oper	ating depth or	
	and the dissourie main	tenance note cove	rs? L Yes L No		
Tank 	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remove			-		
Tank #1 12 50 gal Tank #2	gal Pretreatment	tankga	l Pump Tank	gal	
5. Other information: List any troubleshooting	g, minor repairs cor	ducted, tank safet	y concerns, or other	concerns.	
			,		
, F					
6. Location of septage disposal:	9				
Pinky	y's Environmental Se	wer Service Inc.			
	PO Box 35				

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673