

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to performing maintenance activities	o constitute a va	alid maintenance pon- n-site for the durat	ermit. This permit r	must be completed
Date of Maintenance: 5-4-19 Reason f	or Maintenance:	Partine	3	
Property Address: 1600 Quant Ave.				recks
Municipality: ARTO ZIP: 550	Property Ide	ntification Number:		
1 0 1 1			y's Environmental Se	wer Service / 1 1673
	The Bridge Steen in the constitution of the Bridge Steen Constitution of Standard Standard Steen Constitution of Standard		y a controlled se	wer service/ £10/3
Maintenance Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped	Liquid Level of Tank — in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25%				if 25% or greater
evidence of damaged, cracked, or structural Tank	ly unsound main Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ Mo	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 gal Tank #2 g	gal Pretreatment	tankga	l Pump Tank	gal
5. Other information: List any troubleshooting, n				
6. Location of septage disposal:	/			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.