

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a va	alid maintenance p	ermit. This permit r	nust be completed
prior to performing maintenance activiti	es and remain or	n-site for the durat	ion of the maintena	nce activity.
Date of Maintenance: 4-26-18 Reason	for Maintenance:	Routine		
Property Address: 6339 St Crox	In. So	Property Owner's N	lame: Donna	Dearin an
Municipality: Hastengs ZIP.550	25	ntification Number		The way of
7				
Maintenance Permit No: 14106 x 10051 M	aintainer Name a	nd License No. <u>Pink</u>	y's Environmental Se	wer Service/ L1673
Maintenance Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Tank — in		
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenan	ce Hole Other (enter authorization co	ode)	
2. Were all covers securely replaced? Yes				
3. Is there evidence of tank leakage from a sept		reatment or pump	tank below the oper	ating depth or
evidence of damaged, cracked, or structura	lly unsound main	tenance hole cove	rs? 🗌 Yes 🗆 No	3
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 gal Tank #2 400	gal Pretreatment	tankga	al Pump Tank	gal
5. Other information: List any troubleshooting,	minor repairs see	nducted tank safe	ty concerns or otho	
	illillor repairs coi	iducted, talik sale	cy concerns, or othe	r concerns.
System too old for manhot				
System too old for manhot	B			
	B			

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.