

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit	must be completed	
<u>prior</u> to perfo	rming maintenance activit	ies and remain or	-site for the durat	ion of the maintena	ance activity.	
Date of Maintenance:	<u>4.21-18</u> Reason	for Maintenance:	Renting			
Property Address:	1375 1484 51	Mc	Property Owner's N	ame: Rupet	Ronalle	
Municipality: STI	WUTU ZIP: 550	\$2 Property Ide	ntification Number:			
	10: j 8763h 10386 M					
		tarreamer Hame a	id License No. Filik	y s chvironinentat se	ewer Service/ L16/2	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank ——— in				
\square Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	nove septage: Maintenan	nce Hole Other (e	enter authorization co	ode) To Dil-	Bimmhile	
	curely replaced? Yes					
	The second secon		eatment or numn	tank balow the ana	wation double	
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed?				C.,,	
Tank #1 1200	gal Tank #2	gal Pretreatment	tankga	l Pump Tank	gal	
5. Other information:	List any troubleshooting,	minor repairs cor	ducted, tank safet	y concerns, or other	er concerns.	
		<i>n</i> -				
Location of septage	disposal: 50%	m				
	Pinky's	Environmental Se	wer Service Inc.			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.