

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenan

			site (of the dail	The same of the sa	ince activity.	
Date of Maintenance: 🚄	7.24-18 Reason	on for Maintenance:	Compliance	Insp.		
roperty Address: 197			1	Name: Richard + Pa	+ Le Pour	
lunicipality:Marin	2 ZIP: 55	7 Property Id	entification Numbo	Pt	The Root	
aintenance Permit No:		Alaintaines Mana	and the control wallings			
	C01011110101.	maintainer Name a	and License No. Ols	on's Sewer Service/L	216	
			i			
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
∑ Tank(s) Pumped ☐ Sludge and scum measured		Liquid Level of	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in			
		Sludge Level in				
Do tanks need to be	pumped?	Studge + Scum	/ Liquid	Level X 100		
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
Access were did		<u> </u>				
. Access used to remov	e septage: Mainten	ance Hole \sqcup Other (enter authorization of	code)		
. Were all covers secur	ely replaced? 🔯 Yes	□No				
. Is there evidence of t	ank leakage from a se	ntic holding prot	reatment or nume	damle halanı ili a anan	- 42 4 44	
evidence of damage	d, cracked, or structu	rally unsound mair	tenance halo sov	tank below the oper	ating depth or	
				ers: L Yes L No		
_	Tank	Leaking Out	Leaking in	Cover Damage		
Se	eptic/Holding Tank #1	☐ Yes 🗷 No	☐ Yesc 🗆 No	☐ Yes 🏹 No		
Se	eptic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pro	etreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pu	Imp Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
How many gallons of s	eptage were removed	! ?				
Tank #1 / 3010 ga		gal Duatemeter and	tank	ol Bumon Toule		
	રા Tank #2	– gat Pretreatment	Latin 02		~~!	
Other information: Lis	al Tank #2st any troubleshooting	- gat Pretreatment . minor repairs cor	ducted tank safe	ty sonsorns, or other	gal	
Other information: Lis	al Tank #2 it any troubleshooting	, minor repairs cor	nducted, tank safe	ty concerns, or other	gal r concerns.	
Other information: Lis	al Tank #2 it any troubleshooting	, minor repairs cor	nducted, tank safe	ty concerns, or other	concerns.	
Other information: Lis Location of septage dis	any troubleshooting	, minor repairs cor	nducted, tank safe	ty concerns, or other	gal r concerns.	

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082