

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	e completed in its entirety	to constitute a v	alid maintenance p	ermit. This permit r	nust be completed
<u>prior</u> to perfo	orming maintenance activity	ies and remain or	n-site for the durat	tion of the maintena	nce activity.
Date of Maintenance:	1 7 1 1		Routin		
Property Address: 1	51 Tonglewa	Lh.	Property Owner's N	lame: LOY i So	ykup.
Municipality: <u>M</u>			entification Number		
Maintenance Permit I	NO:014534611067 M	laintainer Name a	nd License No. Pink	xy's Environmental Se	wer Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Sc	um Ta	nks must be pumped	if 25% or greater
1. Access used to rea	move septage: Maintenan	ce Hole Other (
3. Is there evidence	of tank leakage from a sept aged, cracked, or structura Tank	ic, holding, pret	reatment or pump	tank below the oper	ating depth or
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑No	☐ Yes 🖺 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons Tank #1 1500	of septage were removed?gal Tank #2	gal Pretreatmen	The state of the s		gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or other	r concerns
	e disposal: S+, Pau				
	Pinky's	Environmental Se			
		PO Box 35	4		

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.