

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	ampleted in its entirety to	constitute a valid	maintenance per	mit. This permit mu	ist be completed
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Worth					
Date of Maintenance: 6-14-18 Reason for Maintenance:					
Property Address: 12515 Kellev Ave N Property Owner's Name: Dave Dobrotka					
Municipality: Hugb ZIP: 55038 Property Identification Number:					
Maintenance Permit No: 631301765 Maintainer Name and License No. Pinky's Environmental Sewer Service/L1673					
Manreen and Control					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2 Were all covers securely replaced? ☐ Yes ☐ No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? \square Yes \square No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 17 90 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
6. Location of septage disposal:					
Pinky's Environmental Sewer Service Inc.					
PO Box 354					
Afton MN 55001					

Maintenance activities must be reported to the Department within 90 days.

P: 651-439-4847 License Number: L1673