

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to	o constitute a va	alid maintenance p	ermit. This permit	must be completed
<u>prior</u> to performing maintenance activitie Date of Maintenance:			ion of the maintena	nce activity.
	or Maintenance:			
Property Address: 9895 53rd St. 1	SC	Property Owner's N	ame: <u>)(MN M</u>	enwillen
Municipality: We Elmo zip: 5504	2 Property Ide	entification Number		
Maintenance Permit No: W 1983 V 10938 Ma				wer Service / L1673
			, and the second	Wel Selvice/ E10/5
Maintenance Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped	Liquid Level of	Tank ——— in		
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: \square Maintenance	e Hole Other (e	enter authorization co	ode)	
2. Were all covers securely replaced? Yes	No	to old		
3. Is there evidence of tank leakage from a seption			tank below the oper	ating depth or
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes				
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☑ No	☐ Yes ☑No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 See gal Tank #2g	al Pretreatment	tankga	l Pump Tank	gal
Tank #1 gal Tank #2 gal 5. Other information: List any troubleshooting, m	al Pretreatment	tankga	l Pump Tank	gal r concerns.
Tank #1 See gal Tank #2g	al Pretreatment	tankganducted, tank safet	l Pump Tank	gal r concerns.
Tank #1 See gal Tank #2gal 5. Other information: List any troubleshooting, m	inor repairs cor	iducted, tank safet	y concerns, or othe	r concerns.
Tank #1 See gal Tank #2g	inor repairs cor	iducted, tank safet	l Pump Tank	r concerns.
Tank #1 See gal Tank #2gal 5. Other information: List any troubleshooting, m	inor repairs cor	iducted, tank safet	y concerns, or othe	r concerns.

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.