

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety to	constitute a vali	d maintenance pe	rmit. This permit mu	st be completed
prior to perfor	ming maintenance activitie	s and remain on-	site for the duration	on of the maintenanc	e activity.
Date of Maintenance:	6-11-18 Reason fo	r Maintenance: _	Zoutiva	_	
Property Address: 75	830 110th St. S	P	roperty Owner's Na	me: Paul Co	cchiapell
Municipality: CHUC	y Gru ZIP: 5500	Property Iden	tification Number:		_
Maintenance Permit N	0: £8044511156 Ma	intainer Name an	d License No. Pinky	's Environmental Sew	er Service/ L167
					· · · · · · · · · · · · · · · · · · ·
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank ———— in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	nove septage: Maintenand	e Hole Other (e	nter authorization co	de) Tanking	flower
2. Were all covers securely replaced? ☐ Yes ☐ No					
3. Is there evidence	of tank leakage from a sept	ic, holding, pretr	eatment or pump	tank below the opera	ting depth or
evidence of dama	aged, cracked, or structura	ly unsound main	tenance hole cover	rs? 🗌 Yes 🗹 No	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1/2_50	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or other	concerns.
		2 1 1 1 1			
6. Location of septag	e disposal:	and			
	Pinky's	s Environmental S	ewer Service Inc.		
		PO Box 3	54		
		Afton MN 5	5001		
	5 (5)	120 1017 1:	N 1 1 (72		

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.