

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	ty to constitute a va	lid maintenance p	ermit. This permit	must be completed	
<u>prior</u> to performing maintenance acti					
2 11 10	on for Maintenance:				
Property Address: 13141 22nd 5	t. MO.	Property Owner's N	ame: Ardell	Finnemany	
Municipality: Stillwato zip: 5	Property Ide	ntification Number			
Maintenance Permit No: 3994301152	_ Maintainer Name ar	nd License No. <u>Pink</u>	y's Environmental Se	ewer Service/ L167:	
Maintenance Performed	Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank ——— in			
Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measuremen	ts) = % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: \Box Mainte	nance Hole Other (e	enter authorization co	oder Tarkin du	side walk	
2. Were all covers securely replaced? \(\square\)			timberd see		
3. Is there evidence of tank leakage from a s	septic, holding, pretr	eatment or pump	tank below the one	rating denth or	
evidence of damaged, cracked, or struct	urally unsound main	tenance hole cove	rs? Yes No	racing depth of	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remove	ed?				
Tank #1 / 5 D gal Tank #2	gal Pretreatment	tankga	al Pump Tank	gal	
5. Other information: List any troubleshooting	ng, minor repairs cor	ducted, tank safe	ty concerns, or other	er concerns.	
6. Location of septage disposal:					
			49. 18. 10.		
Pinl	ky's Environmental Se	wer Service Inc.			

Maintenance activities must be reported to the Department within 90 days.

PO Box 354 Afton MN 55001