

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	ing maintenance activiti				
Date of Maintenance:	0	for Maintenance:	1	10.	ice activity.
Property Address: 99	2 - 1 - 1	i I		ame: Jana & Mo	aux Pro
4					ir rauer
Municipality: <u>Mauto</u>			ntification Number		
Maintenance Permit No:	16240e 11158 M	aintainer Name a	nd License No. <u>Pink</u>	y's Environmental Sev	wer Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no	provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove	ve septage:  Maintenan	ce Hole Other (	enter authorization co	ode)	
2. Were all covers secui	rely replaced? Yes	No to	Leep		
<ol> <li>Is there evidence of the evidence of damage</li> </ol>	ank leakage from a sept d, cracked, or structura	ic, holding, preto Ily unsound main	eatment or pump tenance hole cove	tank below the oper rs?	ating depth or
_	Tank	Leaking Out	Leaking In	Cover Damage	
Se	eptic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑No	☐ Yes 🖺 No	
Se	eptic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pr	etreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pt	ımp Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of Tank #1 Score g	septage were removed?  al Tank #2  st any troubleshooting,	gal Pretreatment	tankga	ty concerns, or other	gal r concerns.
6. Location of septage di		Environmental Se			
		PO Box 35			
		Afton MN 55	001		

Maintenance activities must be reported to the Department within 90 days.